YPES-15-119

# 090 II, 187, 312, ハイブリッド 防水コネクタ取扱説明書

 $090\,\mbox{I\hspace{-.1em}I}$  , 187, 312, HYBRID Handling Manual for Sealed Connector

注)

本取扱説明書は、発行先に対し連絡無しに改訂する場合がありますので 必要時には最新版を御依頼願います。

> 矢崎総業株式会社 矢崎部品株式会社 2021.01.20

この度は、弊社コネクタを採用頂き有難うございます。


本説明書は、本製品をご使用頂く上で最低限必要な項目を記載したものです。取扱の際には、本記載内容を遵守下さい。

弊社は本内容を遵守しないで起こった損害または誤使用により起こった 損害に対しては責任を負いません。


## 目 次


2. ターミナル及びハウジングの検査 ・ ・ ・ ・ ・ ・ P. 4	
3. 圧着作業について・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	
4. ハーネス製造作業 ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ P. 9 4-1. ハウジングへのターミナル挿入 4-2. 二重係止作業 4-3. ターミナル引抜き作業 4-4. ホルダーの解除方法	
5. ハーネス製品の管理について ・ ・ ・ ・ ・ ・ ・ ・ ・ P. 14 5-1. 検査 5-2. 出荷、運搬、保管	
6. コネクタのかん合及び取りはずし・・・・・・・・・ P. 15 6-1. コネクタのかん合 6-2. コネクタの取りはずし 6-3. コネクタのかん合後の回路チェック	
・ターミナル及びハウジング、ゴム栓一覧表 別紙 1~4 ・二重係止作業の冶具挿入位置代表例一覧表 別紙 5~7	

1. 構成部品と各部名称 1-1. コネクタ構成部品



1-2. 各部名称 1-2-1. ターミナル・メール





## 2. ターミナル及びハウジングの検査

当社検査基準に基づき、完全な検査を行なって出荷しておりますが、該当する製品の顧客用図面の内容について検査されることを望みます。

## 3. 圧着作業について

## 3-1. 保管及び運搬

- ① 保管は梱包箱に入れた状態にて、清浄な屋内で且つ常温常湿(5~35℃、45~85%RH)の環境下に保管願います。
- ② 梱包箱より取り出して運搬する場合には、必ずリールセンターの金属部を持ちリールを 縦にして運搬願います。
- ③ 使用を中断するリールは、リールが解けない様に針金等にて先端をフランジに結んでおいて下さい。

## 3-2. 圧着作業

## 3-2-1. 適用電線


① 自動車用低圧電線 JIS-C-3406

② 090 II: AVS 0.3、AVS 0.5、AVS 0.85、AVS 1.25、AVSS 2.0及び相当品の一本圧着のみに適用します。

187 :AVS 0.3、AVS 0.5、AVS 0.85、AVS 1.25、AVS 2.0、AVS 3.0及び相当品の 一本圧着のみに適用します。

312 :AVS 0.5、AVS 0.85、AVS 1.25、AVS 2、AVS 3、AVS 5、AV 8及び相当品の 一本圧着のみに適用します。

## 3-2-2. 注意事項



## 3-2-3. 圧着時の注意事項と判定基準


ターミナルの圧着には下記の項目について注意をし、重点管理をしてください。

チェック項目	チェック内容	判定基準(例)	原因と対策
	芯線ほつれがないか を見る。	〇 ×ほつれは不可	圧着位置、芯線のほ つれ、クリンパー変 形の確認処理
	導体圧着部バリが ないかを見る。	° × • • • • • • • • • • • • • • • • • •	クリンパーワイドの 幅、アンビルワイド 磨耗の確認、交換
ターミナル	ベルマウスの確認	この面より出ている物は不可 〇ベルマウス ×Rの無い物は	ターミナル送り位置
圧着形状		R部を残す不可	スペーサ、クリンパー の位置確認、調整
	絶縁体下りがないか を見る。	<ul><li>○絶縁体はこの ×絶縁体下りは 不可</li></ul>	圧着位置確認、調整 皮むき長さ確認
	絶縁体カシメがない	○ ×前で絶縁体を	圧着位置確認、調惠
	かを見る。	圧着している物は不可	皮むき長さ確認
, (	芯線出すぎ、芯線 引込みがないかを 見る。	○芯線出 0~1 mm ×左図以外の 寸法は不可	同上
ターミナル つなぎ部バリ	バリがないか見る。	<ul><li>×左図以外の寸法は不可</li><li>は不可</li><li>つなぎ長さ0~0.3 mm</li></ul>	切断位置、シャーブ レードの磨耗確認
ターミナル ねじれ	ねじれがないかを 見る。	×目視でねじれの 確認できるものは 不可	ターミナル送りガイド、クリンパー、アンビル変形位置確認


チェック項目	チェック内容	判定基準(例)	原因と対策
上下方向 ターミナル曲り	ターミナル曲りが ないかを見る。	端子種類     雄ターミナル     雌ターミナル       187     1.0° 以下     1.0° 以下       312     インドダウン>	アンビル高さ、変形確認
		端子種類 雄ターミナル 雌ターミナル 090 II 187 312 3.0° 以下 3.0° 以下	
横方向 ターミナル曲り	曲りがないかを見る。	目視で曲りが確認できるものは不可	アンビル、クリンパー 位置確認
ターミナル変形	ターミナルメール 右図A部分の変形 がないかを見る。 ターミナルフィメール 右図A部分の変形が	○ ×変形は不可 → ○ ○ ○ ○ ○ ×変形は不可 ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○	ターミナル送り面、 クリンパー、アン ビル、形、高さ、位置 確認 同上
圧着形状	ないかを見る。	不可 ×芯線が見えては 不可	ターミナルの足の長 さ、クリンパー、ワイド 確認
	ゴム栓の出すぎ引っ 込みすぎがないかを 見る。	○後足がゴム栓先 端とリップ根元の 間にあること	圧着位置確認、ゴム 栓の電線挿入位置 確認
	ゴム栓のキズ、切れ がないかを見る。	×キズ、切れは 不可	圧着位置確認、クリンプハイト、ワイドの 確認
ゴム栓位置	ゴム栓の出すぎ引っ 込みすぎがないかを 見る。	○絶縁体前端より0~0.5までは可	ゴム栓の電線挿入 位置確認

## 3-2-4. クリンプハイト、ワイドの測定方法

ターミナルと電線との固着力は適用電線毎に異なり、その管理方法としてクリンプハイト(圧着高さ)の管理がある。クリンプハイトは圧着されたターミナルの電気的、機械的性能に影響するので、クリンプハイトが指定の寸法になっているか確認する。



- ① クリンプハイトの測定方法 クリンプハイトは導体圧着部、絶縁体圧着部の中心を測定する。
- ② クリンプワイドの測定方法 クリンプワイドは導体圧着部、絶縁体圧着部下側の一番広い所を測定する。




## 3-2-5. 圧着後の確認事項

ターミナル圧着部強度(ターミナル・電線間) 約100 mmの長さの電線を圧着したターミナル を固定し、電線を軸方向に約200 mm/minの 一定の速度で引張り、電線の破断あるいは 圧着部から電線の引き抜ける時の荷重を測定する。

ターミナル圧着強度

<u> </u>	// 工有 饿 及
電線サイズ(mm²)	性能
0.3	78.4N以上
0.5	88.2N以上
0.85	127.4N以上
1.25	176.4N以上
2	264.6N以上
3	294.0N以上
5	392.0N以上
8	441.0N以上



## 3-3. ターミナル圧着後の製品取扱い


ターミナル圧着済品は、ターミナルの変形、ゴム栓部へのホコリ付着、キズ等が発生しやすい為、 運搬保管には充分注意願います。

## 4. ハーネス製造作業


4-1. ハウジングへのターミナル挿入

- ① 挿入は図の様な方向で挿入します。
- ② ターミナルの挿入は「パチン」という音がするまで確実に挿入します。 「パチン」という音がしたら軽く電線を引張り、確実に掛っていることを確認します。
- ③ ターミナルに圧着したゴム栓後端がハウジングの端子挿入口より中に入っているか確認します。






ハウジング・フィメール ターミナル・フィメール




## 4-2. 二重係止作業

① 仮係止状態のハウジングにターミナルを挿入し、下図のようにスペーサを矢印方向へ押し込む。この時、ターミナル・パッキン及びシール面にキズを付けない様、注意ください。



② スペーサを嵌合面(矢印)まで押し込んでください。




MALE(代表)

FEMALE(代表)


## 4-3. スペーサの解除方法

下図の様に治具(治具品番 1-19(49YA100012)、1-35(49YA000002))を穴に差し込み、 矢印方向へ移動させて仮係止状態へ戻す。

## MALE



**FEMALE** 




仮係止状態

4-3. ターミナルの引き抜き作業 4-3-1. ターミナルの引き抜き治具


治具は、矢崎品番1-15(49YA000056)、1-19(49YA100012)を使用し、他の治具の使用は避けて下さい。

## 4-3-2. ターミナルの引き抜き方

① まず始めに、スペーサを抜き方向に抜き、本係止状態から仮係止状態へ戻す。



② ターミナルとランスの隙間に治具の先端をセットし、治具にて図の様に曲げ、ターミナルの係止穴よりビークを外し、電線を引張り、ターミナルを抜きます。



## 4-3-3. ターミナルを抜く時の注意点


- ① 治具の先端は必ずターミナルとランスの隙間にあることを確認して作業を始めて下さい。
- ② 治具で絶対にこじらないこと。

ターミナル・メール → アライメントがそろわなくなる恐れがあります。

ターミナル・フィメール → カーリングタングを変形させる恐れがあります。

こじった場合は、ターミナルを新しい物と交換して下さい。

③ ターミナル・フィメールを抜く時、誤ってターミナルのタブクリアランス部分に治具を挿入してしまった時は、その多少に関係なくターミナルを新しい物と交換して下さい。



- ④ 引き抜く際、軽く引張って抜けない時は無理に引張らないで再度始めから作業をやり直して下さい。
- ⑤ 引き抜いた後、ターミナルの変形の有無を必ず確認し、変形した物は手直しをしないで新しい物と交換して下さい。

## 5. ハーネス製品の管理について 5-1. 検査


- ① 特定のターミナルに引張り荷重が加わらない様にテープ巻き等に注意して下さい。
- ② 配線検査や導通検査に使用する治具は、コネクタがこじられない様に精度の高いガイドを設けて下さい。
- ③ 導通検査においてメス側に治具を挿入する時は、治具の精度をオスターミナルと同程度管理して下さい。
- ④ コネクタ、ターミナル、ゴム栓の変形や損傷が有った場合は、その多少に関係なく絶対に 手直しを行わないで、新しいものと交換して下さい。
- ⑤ ハウジングフィメールには必ずパッキンが入っていることを確認して下さい。 (7282-7420、7282-7029、7282-8227はハウジングメール側にあります。)
- ⑥ ゴム栓は必ずハウジング内に入っていることを確認して下さい。

## 5-2. 出荷·運搬·保管

① 塵芥、雨水等を防止し、丁寧に取扱う様にお願いします。

## 注意事項

部品の納入状態が、もし下図の様な場合、端子の挿入が出来ませんので恐れ入りますが治具にて仮係止状態までもどして下さい。



端子挿入不可

治具にて仮係止状態まで戻す


注意:ホルダの上下において爪の変形、 破損した物はハウジングを交換して 下さい。

(M,F同様)

## 6. コネクタのかん合及び取りはずし


## 6-1. コネクタのかん合

- ① 図の様にロッキングレバーとロッキングビットを同方向に合わせ、こじらない様にかん合します。
- ② 必ずロックの掛るまで確実に挿入し、かん合後は軽く引っ張ってロックが掛っている事を 確認願います。




## 6-2. コネクタの取りはずし

- ① ロッキングキーを押してロックを解除してから、引っ張って取りはずして下さい。
- ② 電線を持って引っ張る事は避けて下さい。



## 6-3. コネクタかん合後の回路チェック

テスター等で導通や電圧等を調べる場合、チェックしたいコネクタにその相手側と同一の コネクタをかん合しチェックして下さい。



## <ターミナル及びハウジング,ゴム栓一覧表>

# ◎ターミナル 090 II ターミナル

種別	矢崎品番	電線サイズ
	7114-4025	AVS 0.3
J	7114-4025-08	AVS 0.5
メー	7114-4026(すずめっき)	AVS 0.5
ル	7114-4026(9 9 8)ろさ) 7114-1461(金めっき)	AVS 0.85
,,,	1114 1401(巫(グ)つる)	AVS 1.25
	7114-4027	AVSS 2.0
7	7116-4025	AVS 0.3
フ	7116-4025-08	AVS 0.5
イメ	7110 1000(ナデザーを)	AVS 0.5
<u> </u>	7116-4026(すずめっき) 7116-1461(金めっき)	AVS 0.85
ル	1110 1401(亚沙)(36)	AVS 1.25
	7116-4027	AVSS 2.0

## 187 ターミナル

101 /	× / / / ·	
種別	矢崎品番	電線サイズ
	7114 4025	AVS 0.3
	7114-4035	AVS 0.5
メ		AVS 0.5
	7114-4036	AVS 0.85
ル		AVS 1.25
	7114-4037	AVS 2.0
		AVS 3.0
	7116-4035	AVS 0.3
フ		AVS 0.5
フィメ		AVS 0.5
		AVS 0.85
		AVS 1.25
ル	7116-4037	AVS 2.0
	1110-4037	AVS 3.0

012//	1770	
種別	矢崎品番	電線サイズ
4	7114 6045	AVS 0.5
,	7114-6045	AVS 1.25
メ	7114-6046	AVS 2
ル	7114-0040	AVS 3
	7114-6047	AVS 5
		AV 8
フ	7116-6045 7116-6046	AVS 0.5
		AVS 1.25
イメ		AVS 2
	7110-0040	AVS 3
ル	7116-6047	AVS 5
,,,	7110-0047	AV 8

## ◎ハウジング

## 090Ⅱ ハウジング

090 H ハワシンク		矢崎部品番号		
			ハウジング	
極数	種別	サブアッシー	ホルダー	
			パッキン	
			7183-1015-10	
	フィメール	7283-1015-10	7157-4355	
			7137-2602-80	
			7183-1018-40	
1極	フィメール	7283-1018-40	7157-4355	
			7137-2606-40	
			7183-1019-40	
	フィメール	7283-1019-40	7157-4355	
			7137-2606-60	
			7183-7526-80	
	フィメール	7283-7526-80	7157-4356	
			7137-2603-30	
			7183-1224-30	
	フィメール	7283-1224-30	7157-4353	
			7137-2247-80	
			7183-7027-40	
	フィメール	7283-7027-40	7157-4347	
			7137-2240-30	
		7282-7028-30	7183-7028-30	
	メール		7157-4349	
			7100 7000 00	
د احد	フィメール	7283-7028-30	7183-7028-30	
2極			7157-4350	
			7137-2244-30	
	) 3	7000 7400 40	7183-7420-40	
	メール	7282-7420-40	7157-4349	
			7137-2245-30	
	メール	7282-7029-40	7183-7029-40 7157-4349	
			7137-2245-30	
			7183-7029-40	
	フィメール	7283-7029-40	7157-4352	
		1203-1029-40	7137-4332 -	
			7183-8221-30	
	フィメール	7283-8221-30	7157-4360	
	17. 10	1400 0441 00	7137-2607-30	
			7183-1133-30	
	フィメール	7283-1133-30	7157-4361	
,	ノイグール	1283 <sup>-</sup> 1133 <sup>-</sup> 30	7137-2608-30	
3極		7283-7030-30	7183-7030-30	
	フィメール		7157-4116	
	ノイメール		7137-2213-80	
			1131-4413-00	

(090 Ⅱ)		矢崎部品番号	
極数	種別	サブアッシー	ハウジング ホルダー パッキン
5極	フィメール	7283-7050-30	7183-7050-30 7157-4117 7137-2241-30
	フィメール	7283-7052-30	7183-7052-30 7157-4348 7137-2241-30
6極	メール	7282-7062-40	7182-7062-40 7157-4120 -
	フィメール	7283-7062-40	7183-7062-40 7157-4121 7137-2243-30

## 187 ハウジング

		矢崎部品番号	
極数	種別	サブアッシー	ハウジング ホルダー
			パッキン 7182-7043-40
	メール	7282-7043-40	7157-4118
4極			7100 7040 40
			7183-7043-40
	フィメール	7283-7043-40	7157-4119
			7137-2242-30

## 312 ハウジング

		矢崎i	部品番号	
			ハウジング	
極数	種別	サブアッシー	ホルダー	
			パッキン	
1極	メールフィメール	7282-3013-30	7182-3013-30	
			7157-4358	
			_	
				7183-3013-30
		7283-3013-30	7157-4359	
			7137-2605-30	

## ハイブリッド ハウジング

		矢崎部品番号	
極数	種別	サブアッシー	ハウジング ホルダー パッキン
090 II 2極	メール	7282-7032-30	7182-7032-30 7157-4126 -
+ 187 1極	フィメール	7283-7032-30	7183-7032-30 7157-4127 7137-2601-30
187 2極 +	メール	7282-7046-30	7182-7046-30 7157-4124 -
312 2極	フィメール	7283-7046-30	7183-7046-30 7157-4125 7137-2251-30


## ◎ゴム栓

種別	矢崎品番	適用電線サイズ	材質	色
	7157-3821	AVSS 0.3~AVSS 0.5	シリコン	濃緑
	7157-3646	AVS 0.5~AEX 1.25	シリコン	ベンガラ
090 Ⅱ	7157-3648	AVS 0.3~AVSS 2	NBR	黒
	7157-8761	空 栓	シリコン	ベンガラ
	7157-8767-80	空栓	シリコン	ベンガラ
	7157-8767	空栓	NBR	黒
	7157-3850	AVS 0.3~AVS 1.25	NBR	灰
187	7157-3852	AVS 0.2~AVS 3	NBR	黒
	7157-8763	空 栓	NBR	濃灰
	7157-3853-40	AVS 2~AVS 3	NBR	灰
312	7157-3854	AVS 5~AV 8	NBR	黒
	7157-8764	空 栓	NBR	黒

## <二重係止作業の治具挿入位置代表例一覧表(黒印部分)>

極数	別 MALE	FEMALE
090 Ⅱ 1P		
090 <b>Ⅱ</b> 2P		類似 7283-1018-40
090 II 2P	類似 7282-7029-40 7282-7420-40	類似 7283-7029-40
090 II 3P		

極数種別	MALE	FEMALE
090 II 3P		類似 7283-7030-30
090 II 5P		類似 7283-7052-30
090 II 6P		
187 2P		



YPES-15-119

# Handling Manual for

# 090 II, 187, 312, HYBRID Sealed Connector

Note:

This handling manual is subject to change without notice. Please ask us for the latest version as necessary.

YAZAKI CORPORATION YAZAKI PARTS CO., LTD Jan 20, 2021 Thank you for using our product.


This handling manual specifies the minimum requirements on using this product.

Please always observe all of these requirements when you handle this part.


We shall not be liable for any damage resulting from misuse or failure to follow this handling manual.

## Table of Contents


- 1. Composite parts and the descriptive names
- 1-1 Composite parts
- 1-2 Descriptive names of terminals
- Terminal and housing inspection
- 3. Crimping
- 3-1 Storage and transportation
- 3-2 Crimping
- 3-3 Handling after crimping
- 4. Manufacturing of wiring harness products
- 4-1 Terminal insertion into housing
- 4-2 Double locking
- 4-3 Spacer removal
- 4-4 Terminal removal
- 5. Wiring harness products
- 5-1 Inspection
- 5-2 Shipping, transportation, and storage
- 6. Insertion and removal of connector
- 6-1 Connector insertion
- 6-2 Connnector removal
- 6-3 Circuit check after connector insertion
- < Part number of terminal, housing and rubber seal> Attachment 1-7




## 1-1. Composite parts



1-2. descriptive names 1-2-1. Male terminal





## 2. Terminal and housing inspection

Based on Yazaki standards, thorough inspections are carried out on all terminals and housings. However it is requested that inspection of all manufacturing parts be carried out per the appropriate approval drawing.

- 3. Precautions at crimping
- 3-1 Storage and transportation
  - Parts shall be packed in a box and stored indoors at normal temperature and humdity (5 to 35 degrees C, 45 to 85 %).
  - When transporting parts which are taken out of a box, be sure to hold the metallic area of a reel center and keep the reel in the vertical position.
  - If all terminals are not used and the remaining terminals are to be stored, fix the terminal edges to a reel with a wire in order to avoid fraying.
- 3-2 Crimping specification
- 3-2-1 Applicable wire size
  - 1. Low voltage cable for automobile (JIS-C-3406)
  - 2. 090II ; AVS 0.3, AVS 0.5, AVS 0.85, AVS 1.25, AVSS 2

(Only for a single wire crimping)

187 ; AVS 0.3, AVS 0.5, AVS 0.85, AVS 1.25, AVS 2, AVS 3

(Only for a single wire cimping)

312 ; AVS 0.5, AVS 0.85, AVS 1.25, AVS 2, AVS 3, AVS 5, AV 8


(Only for a single wire cimping)

## 3-2-2 Precautions

1. Diagonal cut



2. Stripping inferiority




3-2-3. Precautions at crimping and the judgement Take care pf the following things at crimping

Check item	Check point	Judging criterion (eg.)	Cause and measur
	Any fraying	○ ×Fraying	Check and fix crimping, location,
			fraying or crimper deformation
	Burr on crimped area		Check and change crimp wire width and anvil width wear
		Should not protrude the line	
Terminal Crimping Shape	Bell mouth	OLeave bell-mouth ×NoRR	Check and adjust location of terminal feeder, spacer and
~ Hupe			crimper
	Insulation falls short of insul. barrel	○Insulation is in × the place	Check and adjust the crimping position. Check stripping length
	Crimped insulation	×Insulation is crimped	Check and adjust the crimping position. Check stripping lengt
, (	Wire protrusion	○ 0~1 mm ×Any dimension expect 0~1 mm	Check and adjust the crimping position.
Burr on terminal	Burr	○ ×Any dimension expect 0~0.3 mm	Check the cutting position and sheer
joint area			blade wear
Terminal	Twist	Joint length 0~0.3 mm	Check position and
twist	2 11200	×Visible	deformation of terminal feeder guide, crimper and anvil.

Check item	Check point	Judging criterion (eg.)	Cause and measur
Terminal bend up and down	Terminal bend	Send up > TYPE   Male terminal   Female terminal   187   1.0°Max. Send down > Send down >	Check the hight of anvil and deformation
		Type   Male terminal   Female terminal	
Terminal bend left and right	Bend -	Any observable deformation by visual inspection isunacceptable	Check the position of anvil and crimper
Terminal deformation	Deformation of A area of male terminal  Deformation of	× Deformation of A area × Deformation of	Check terminal feeder, anvil, shape, hight and position Check terminal
	A area of female terminal	A area	feeder, anvil, shape, hight and position
Crimp shape	Wire exposure	×Wires shall not be seen	Check length of wires, crimper width.
	Position of rubber seal	OInsulation crimp is between tip of rubber seal and root of lip.	Check crimp position and insertion position of wires into rubber seal
	Any cuts on rubber seal	×Cut or tear	Check crimp position, crimp hight and crimp width
Position of rubber seal	Position of rubber seal	○0~0.5mm from the front of insulation	Check insertion position of wires into rubber seal

## 3-2-4 Measrement of crimp height and width

Retention force of terminals to wires depends upon the applicable wire size. To assure this, crimp height must be controlled. Due to the crimp height influencing electrical and mechanical performances of a crimped terminal, the crimp height must be checked to assure the specification is satisfied.




## (1) Measurement of crimp height

Measure the center of wire crimp and insulation crimp.

## (2) Measurement of crimp width

Measure the broadest point of the lower parts of wire crimp and insulation crimp.



## 3-2-5 Confirmation item after crimping


Terminal crimp strength (between terminal and wire)

A terminal which is crimped with wires approximately 100 mm long shall be fixed, and the wires shall be pulled in an axial direction at a speed of 200 mm/min. The load when the wires are removed from the crimped area shall be measured.

Terminal Crimp Strength

Wire size (mm <sub>2</sub> )	Performance
0.3	Over 78.4 N
0.5	Over 88.2 N
0.85	Over 127.4 N
1.25	Over 176.4 N
2	Over 264.6 N
3	Over 294.0 N
5	Over 392.0 N
8	Over 441.0 N






# 3-3 Handling of parts after terminal crimping


During transportation or storage, unprotected crimped terminals and seals are susceptible to damage and/or contamination.

- 4. Manufacturing of wire harness
- 4-1 Terminal insertion into housing
  - (1) Terminals shall be inserted as shown below.
  - (2) Push in the terminal until it clicks. The clicking sound is the audible confirmation that the terminal is inserted. Next pull the wires to assure the terminal is properly inserted.
  - (3) Check to assure the end of the rubber seal is inside the plastic shroud of the housing.



# 4-2 Double locking (for male and female)


(1) Insert a terminal into a housing in a preliminal locking condition, and push a in spacer in the direction that the arrow shows in the picture below. Be careful not to cut the terminal packing or the surface of a seal.



Male (Example)

Female (Example)

(2) Push the spacer as far as the mating surface (the arrow below).




Male (Example)

Female (Example)


## 4-3. Spacer removal

Insert a jig (Yazaki part No. 1-19 (49YA100012), 1-35 (49YA000002)) into a hole as shown below, and move the jig in the direction that the white arrow shows below to put the spacer back in the preliminal locking condition.

Male



Preliminal locking condition



Preliminal locking condition


## 4-4 Terminal removal

## 4-4-1 A jig for terminal removal


A jig shall be 1--80 or 1--15 of Yazaki part number, and avoid using other jigs.

### 4-4-2 How to remove terminals

① Put the spacer which is in a secondary locking position back in a preliminal locking position by removing the spacer in the removing direction.



② Put the tip of a jig into a space between a terminal and a lance and bend the lance with the jig as shown below. Then, remove the beak out of the terminal locking hole and pull wires to remove the terminal.



### 4-4-3 Precautions at terminal removal


- (1) Before removing a terminal, make sure that the tip of a jig is between a terminal and a lance.
- (2) Avoid wrenching with a jig.

Male terminal  $\rightarrow$  The alignment may not be in order.

Female terminal  $\rightarrow$  A curling tongue may be deformed.

A part which is wrenched must be replaced with a new one.

(3) If a jig is inserted in a tab clearance by mistake when removing a female terminal, the terminal must be replaced with a new one with no regard to the degree of its damage.



- (4) If the terminal can not be removed by pulling it lightly, do not try to pull it out by force, repeat the procedure from the start.
- (5) After removing, be sure to check if there is any deformation on the terminal. A deformed terminal must be replaced with a new one.

#### 5 Wiring harness products

#### 5-1 Inspection

- Be careful not to put an excess load on a certain terminal at taping.
- ② A jig to be used for wiring inspection or continuity testing shall be equipped with an accurate guide.
- When inserting a jig into a female side at a continuity test, an accouracy of the jig shall be the same as the male terminal.
- 4 If there is any deformation or cuts on connectors and terminals, relace the part with a new one with no regard to the degree of its damage.


### 5-2 Shipping, transportation and storage

 $\ensuremath{\text{\textcircled{1}}}$  Take a great care to prevent dust, rain and e.t.c..

#### Precaution

If the condition of parts when they are shipped is as the picture below, put a housing back in a preliminal locking position as it is impossible to insert.

### Spacer in a secondary locking





A terminal can not be inserted.





Spacer in a preliminal locking






Put it back into a preliminal locking condition by a removal jig.


Caution: Deformed or cut claw of a spacer must be replaced.
( for both male and female)

- 6. Connector insertion and removal
- 6-1 Connector insertion
  - ① Mate a connector with a locking lever and a locking pit facing each other as shown below. Do not wrench while mating.




### 6-2 Connector Removal

- ① Release the lock by pushing the locking key. Then, pull to remove.
- ② Avoid holding the wires to pull.



# 6-3 Circuit check after connector insertion

When a tester is used to check voltage and so on, a connector to be checked shall be mated to a connector of the same kind.



 $\leq$  Part number of terminal, housing and rubber seal  $\geq$   $\circledcirc Terminal$ 

## 090 II Terminal

	Yazaki part No.	Wire size
71	7114-4025	AVS 0.3
	7114-4020	AVS 0.5
Male	7114-4026(Sn)	AVS 0.5
Maie	7114-1461(A <sub>11</sub> ) AVS	AVS 0.85
		AVS 1.25
	7114-4027	AVSS 2.0
	7116-4025	AVS 0.3
	7110-4020	AVS 0.5
Female	7116-4026(Sn)	AVS 0.5
remaie	7116-4026(Sh) 7116-1461(Au)	AVS 0.85
	/110 <sup>-</sup> 1461(Au)	AVS 1.25
	7116-4027	AVSS 2.0

### 187 Terminal

	Yazaki part No.	Wire size
	7114 4005	AVS 0.3
	7114-4035	AVS 0.5
		AVS 0.5
Male	7114-4036	AVS 0.85
		AVS 1.25
	7114-4097	AVS 2.0
	7114-4037	AVS 3.0
	7116-4035	AVS 0.3
	7110-4055	AVS 0.5
		AVS 0.5
Female	7116-4036	AVS 0.85
		AVS 1.25
	7116-4037 AV	AVS 2.0
	1110 4031	AVS 3.0

### 312 Terminal

OIZ TOTALL			
	Yazaki part No.	Wire size	
		AVS 0.5	
	7114-6045	AVS 0.85	
		AVS 1.25	
Male	7114-6046	AVS 2	
	7114-0040	AVS 3 AVS 5 AV 8	
	7114-0047	AVS 5	
	7114-6047	AV 8	
		AVS 0.5	
	7116-6045	AVS 0.85	
		AVS 1.25	
Female	7116-6046	AVS 2	
	7110-0040	AVS 3	
	7116-6047	AVS 5	
		AV 8	

# $\bigcirc Housing$

# 090 II Housing

		Yazaki part No.		
No. of			Housing	
poles	Type	Sub assembly	Holder	
poies			Packing	
			7183-1015-10	
	Female	7283-1015-10	7157-4355	
			7137-2602-80	
			7183-1018-40	
1P	Female	7283-1018-40	7157-4355	
			7137-2606-40	
			7183-1019-40	
	Female	7283-1019-40	7157-4355	
			7137-2606-60	
			7183-7526-80	
	Female	7283-7526-80	7157-4356	
			7137-2603-30	
			7183-1224-30	
	Female	7283-1224-30	7157-4353	
			7137-2247-80	
			7183-7027-40	
	Female	7283-7027-40	7157-4347	
			7137-2240-30	
	Male	7282-7028-30	7183-7028-30	
			7157-4349	
o.P.	Female	7283-7028-30 7282-7420-40	7183-7028-30	
2P			7157-4350	
			7137-2244-30	
	3.5.1		7183-7420-40	
	Male		7157-4349	
			7137-2245-30	
	3.4.1	7282-7029-40	7183-7029-40	
	Male		7157-4349	
			7137-2245-30	
l l		<b>5</b> 000 <b>5</b> 000 40	7183-7029-40	
	Female	7283-7029-40	7157-4352	
			- - - 	
	TD 1	<b>5</b> 000 0001 00	7183-8221-30	
l i	Female	7283-8221-30	7157-4360	
			7137-2607-30	
	Fomala	7909-1199-90	7183-1133-30	
	Female	7283-1133-30	7157-4361	
3P			7137-2608-30	
	173.	7283-7030-30	7183-7030-30	
	Female		7157-4116	
			7137-2213-80	

(090Ⅱ)		Yazaki part No.	
No. of			Housing
poles	Type	Sub assembly	Holder
poies			Packing
			7183-7050-30
	Female	7283-7050-30	7157-4117
5P			7137-2241-30
91	Female	7283-7052-30	7183-7052-30
			7157-4348
			7137-2241-30
			7182-7062-40
	Male	7282-7062-40	7157-4120
6P			-
θP			7183-7062-40
	Female	7283-7062-40	7157-4121
			7137-2243-30

# 187 Housing

		Yazaki	part No.
No. of	_		Housing
poles	Type	Sub assembly	Holder
poies			Packing
			7182-7043-40
	Male	7282-7043-40	7157-4118
4P			
41			7183-7043-40
	Female	7283-7043-40	7157-4119
			7137-2242-30

# 312 Housing

		Yazaki	part No.
No. of			Housing
poles	Type	Sub assembly	Holder
poies			Packing
			7182-3013-30
	Male	7282-3013-30	7157-4358
1P			-
117			7183-3013-30
	Female	7283-3013-30	7157-4359
			7137-2605-30

# Hybrid Housing

		Yazaki part No.	
No. of			Housing
	Type	Sub assembly	Holder
poles			Packing
090 II			7182-7032-30
2P	Male	7282-7032-30	7157-4126
4F +			-
-			7183-7032-30
187	Female	7283-7032-30	7157-4127
1P			7137-2601-30
187			7182-7046-30
2P	Male	7282-7046-30	7157-4124
4F +			-
•			7183-7046-30
312	Female	7283-7046-30	7157-4125
2P			7137-2251-30

## $\bigcirc$ Rubber seal

Type	Yazaki part No.	Wire size	Material	Color
	7157-3821	AVSS 0.3~AVSS 0.5	Silicone	Dark green
	7157-3646	AVS 0.5~AEX 1.25	Silicone	Red-iron
090 II	7157-3648	AVS 0.3~AVSS 2	NBR	Black
09011	7157-8761	Plug	Silicone	Red-iron
	7157-8767-80	Plug	Silicone	Red-iron
	7157-8767	Plug	NBR	Black
	7157-3850	AVS 0.3~AVS 1.25	NBR	Gray
187	7157-3852	AVS 0.2~AVS 3	NBR	Black
	7157-8763	Plug	NBR	Dark gray
	7157-3853-40	AVS 2~AVS 3	NBR	Gray
312	7157-3854	AVS 5~AV 8	NBR	Black
	7157-8764	Plug	NBR	Black

<Example of jig insertion position for double locking (Black marked area)>

	MALE	FEMALE
090 Ⅱ 1Р		Similar part 7283-1018-40
090 II 2P		
090 II 2P	Similar part 7282-7029-40 7282-7420-40	Similar part 7283-7029-40
090 П ЗР		

	MALE	FEMALE
090Ⅱ 3P		
		Similar part 7283-7030-3
090Ⅱ 5P	Sin	nilar part 7283-7052-30
090 II 6P		
187 2P		

